

NO. - 002-T

CHANGE NOTICE

PERCOM

PART NO. 410-1190-001 & 301-0017-001 REV E

NAME TED/III CONTROLLER Rev D

SUBMITTED BY: H. Mauch

DATE JAN. 27, 1982

APPD H. Mauch

29 Jan 82

DFTG

CHK Barbara Robertson

Jan 29, 1982

CHANGE:

A. CONNECT PIN-2 AND PIN-3 OF U18.

B. CURRENT STOCK TO HAVE THESE CONNECTED BY BARE BUSS WIRE #24 OR SMALLER ON SOLDER SIDE OF BOARD.

C. ADVISE PCB SHOP TO CORRECT FILM AS INDICATED.
CIRCUIT LAYOUT OF BOARD SHOULD SHOW REV ED. NO ENGINEERING ACTION REQUIRED UNTIL NEXT MAJOR DESIGN REVISION.
SCHEMATIC IS CORRECT AS DRAWN.

JANE - ✓

MOSES -

REASON: By connecting these two circuits it will work with
the 8" drives

ADD

